

L Number	Hits	Search Text	DB	Time stamp
3	4	(( "6333790" ) or ( "6631008" )) . PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 09:55
8	38993	ASIC	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 12:44
9	74	printer\$5 near2 controller\$5 with ASIC\$2	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 12:45
10	42	(printer\$5 near2 controller\$5 with ASIC\$2) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 13:32
11	2	("6113208") . PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:27
12	0	(CRC\$4 with (printer\$5 near2 control\$5 near2 (program\$5 softwar\$5 firmwar\$5)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:28
13	0	(CRC\$4 same (printer\$5 near2 control\$5 near2 (program\$5 softwar\$5 firmwar\$5)))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:28
14	2	("6665089") . PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:44
15	5448	(358/1.15) . cccls.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:44
16	136	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5 integrat\$5 complianc\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:45
17	28	((358/1.15) . cccls. ) and ((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5 integrat\$5 complianc\$5) )	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:45
18	11	((358/1.15) . cccls. ) and ((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) and (compatibl\$5 integrat\$5 complianc\$5) ) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/20 14:45
-	229	(printer\$5 near3 controller\$5) with (IC\$2 integrat\$5 near2 circuit\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 13:25

	133	((printer\$5 near3 controller\$5) with (IC\$2 integrat\$5 near2 circuit\$5)) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 13:30
	21	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (integrat\$5 near4 circuit\$5 IC\$2)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:51
	10	((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (integrat\$5 near4 circuit\$5 IC\$2) ) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 17:03
	2	2 ("5580177").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	0	(2002/0041388).CCLS.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	1	2002/0041388	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	0	2002/0041388a1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	0	20020041388a1	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	3	"20020041388"	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:18
	8	((("6606669") or ("6047129") or ("6138178")).PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:19
	2	("6438643").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 14:27
	63	pcrd	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:48
	5	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (compatibl\$5 integrat\$5 complianc\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:53
	549	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:53

-	4	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (compatibl\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:54
-	34	(printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (external\$5)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 16:54
-	16	((printer\$5 near2 control\$5) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5)) same (external\$5)) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 17:02
-	17683	(printer\$5 with (print\$5 near2 controller\$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 17:02
-	129	(printer\$5 with (print\$5 near2 controller\$5)) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 19:25
-	57	((printer\$5 with (print\$5 near2 controller\$5)) same (updat\$4 upgrad\$5 install\$5 replac\$5) same (printer\$5 near2 (driver\$5 program\$5 software\$5 firmware\$5))) and @ad<20000929	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2004/04/19 17:06
-	2	("6538762").PN.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM TDB	2004/04/19 17:07